

Designed by Greta M. Grossman

PRODUCT COLORS





//American walnut/black laminate



Item no.:10013FH-01-07

DESCRIPTION

The desk and dressers are made of American Walnut veneer combined with high-gloss black laminate cabinet and top. The legs are made in black powder coated steel and the knobs are solid American Walnut, either black lacquered or with a clear lacquer. The "62-series" consists of: Desk, Dresser 3, Dresser 4 and Dresser 6. The "62-series" is made to order.

VERSION

RAL codes are indicative.

- American Walnut veneer / black laminate / Black powder coated legs // gloss 20-30 / high gloss / -

TABLE VERSION

Order item - look for part number in the pricelist.

The series consists of the following:

DESK - Table with cabinet on the left side DRESSER 3 - Dresser with 3 drawers and one cabinet

DRESSER 4 - Dresser with 4 drawers

DRESSER 6 - Dresser with 2x3 drawers

FACTS

MEASUREMENT - L x W x H mm Lenght: 1200mm Width: 600mm Height: 720mm

Tabletop thickness: 20mm

WEIGHT ITEM 50 kg

PACKAGING TYPE
No standard packaging


PACKAGING MEASUREMENT - $L \times W \times H CM$ L:128 \times W:69 \times H:88 cm

WEIGHT PACKAGING - TOTAL

55 kg

NUMBER OF PARCELS

1 pcs.







Designed by Greta M. Grossman

ACCESSORIES

CLEANING AND MAINTENANCE

For dusting and light cleaning of the soft coated surface use a soft, dry cloth.

For cleaning the soft coated surface, best results are achieved by means of a brush and concentrated or lightly thinned detergents. Before cleaning, wet surface evenly. Afterwards rinse with water or solvents to avoid a build-up of remainders of detergents, which may, in time, prove difficult to remove.

Dust, fingermarks and stains caused by things water-soluble such as jam, fruit juice etc. are cleaned by

means of a soft brush, moist sponge or cloth. Removal is facilitated by using aqueous detergents, washing-up liquid or methylated or mineral spirit.

Stains caused by mineral oil, lubricants, animal or vegetable oils or fats are cleaned by means of a cloth, sponge or brush used with methylated spirit, isoprophyl alcohol or mineral spirit.

For dusting and light cleaning of the frame use a soft, dry cloth.

For further cleaning, use a soft cloth that is firmly wrung in clean water for gently wiping the surface, and then immediately use a dry cloth to wipe the surface again.

If more thorough cleaning is necessary, use a mild detergent or washing-up liquid dissolved in water on a firmly wrung cloth to wipe the seat. Afterwards repeat the process as described above.

Polish with a soft cloth after wiping.

Do not use materials for cleaning that:

- Contain abrasive agents.
- · Are basic, acidiferous or organic

For the best maintenance of the product, protect it against sunlight and heat, and try to keep it away from moisture, grease and other dirt.

To avoid stains, use coasters or mats under flower pots, vases, cups, glasses etc.

Furthermore, protect the surfaces against sharp objects and other that might scratch.

ENVIRONMENT

Parts can be separated and sorted for recycling.

Disposal of plastic type PP may be done with incineration of waste.

TESTS

CERTIFICATION AND LABELS